#### NATIONAL ASSEMBLY

#### **FOR WRITTEN REPLY**

#### **QUESTION 945**

# DATE OF PUBLICATION IN INTERNAL QUESTION PAPER: 18 MARCH 2022 (INTERNAL QUESTION PAPER NO 11-2022)

#### 945. Mr A G Whitfield (DA) to ask the Minister of Police:

With reference to the Public Order Police Unit, (a) by what date will recruitment of the shortfall of approximately 6 000 officers to the specified unit commence, (b) what is the (i) current intake for the 2020-21 financial year and (ii) projected intake for the 2021-22 financial year, (c) what total number of vehicles are (i) currently operational and (ii) not operational and what are the relevant details thereof in each case and (d) what is the current total number of firearms and ammunition?

**NW1188E** 

#### **REPLY:**

- (a) The South African Police Service (SAPS): Human Resource Management Plan, for 2022/2023, is for 4 000 new police recruits to be trained and allocated to capacitate the Public Order Policing (POP). The training of the recruits will commence, in April 2022 and conclude, in December 2022, after which they will report to POP units.
- (b)(i)(ii) The SAPS was not able to train police recruits, in 2020/2021 and 2021/2022, due to the COVID-19 Pandemic and the Regulations promulgated, in terms of the Disaster Management Act, which placed restrictions on gatherings.
- (c)(i)(ii) As at 14 April 2022, the information regarding the number of vehicles operational, not operational and the relevant details thereof, in each case, is attached as **annexure A**.
- (d) The number of firearms and ammunition of the POP, is of an operational and tactical nature and making this information available, may compromise the operational integrity and negatively affect national security.

## Reply to question 945 recommended/not recommended

NATIONAL COMMISSIONER: SOUTH	
Wanny	GENERAL
NATIONAL COMMISSIONER: SOUTH	I AFRICAN POLICE SERVICE
SF MASEMOLA	

Date: 2022-04-26

Reply to question 945 approved/not approved

MINISTER OF POLICE GENERAL BH CELE, MP

Date:

### Annexure A

	NORTH WE	
	Potchefstro	om
(c)(i) Currently operational	(c)(ii) Not operational	Relevant details thereof in each case
Soft tops: 23	BSK457B (Soft top)	Mechanical fault (gearbox)
Nyalas: 6	BVZ687B (Soft top)	Panel beating
Trucks: 2	BTH838B (Soft top)	Engine fault
	BVF146B (Soft top)	Engine fault
	BTJ633B (Soft top)	Starter fault
	BSM932B (Soft top)	Waiting for tyres
	BTJ221B (Soft top)	Brake system fault
	BNZ009B (Nyala)	Service and doors leaking air
	BJF740B (Nyala)	Engine fault
	BJV124B (Nyala)	Electrical fault
	BJV118B (Nyala)	Alternator fault
	CD37MHGP (Nyala)	Service and battery
Total: 31	Total: 12	
	Vryburg	96.7
Soft tops: 7	BRW882B (Soft top)	Brake system fault
Nyalas: 2	BTH842B (Soft top)	Panel beating
Trucks: 0	BTX996B (Soft top)	Panel beating
	BSB856B (Soft top)	Air conditioner/fan belt
	BJV109B (Nyala)	Electrical fault/Doors leaking air
	BKB897B (Nyala)	Electrical fault/Doors leaking air
	BKB903B (Nyala)	Electrical fault/Doors leaking air
	BTH223B (Truck)	Battery/Starter fault
Total: 9	Total: 8	
	Rustenbur	g
Soft tops: 23	BTJ220B (Soft top)	Recommended for boarding
Nyalas: 6	BTR118B (Soft top)	Recommended for boarding
Trucks: 2	BTJ632B (Soft top)	Recommended for boarding
	BSL853B (Soft top)	Recommended for boarding
	HDN793NW (Soft top)	Recommended for boarding
<u> </u>	BJV092B (Nyala)	Engine repair
	BJW614B (Nyala)	Engine repair
Total: 31	Total: 7	
	Klipgat	
Soft tops: 5	BTP891B (Soft top)	Mechanical repairs
Nyalas: 2	BWG574B (Soft top)	Waiting for registration
	BWD337B (Soft Top)	Repair brakes
	BVJ671B (Nyala)	Windscreen crack, electrical fault
	CD37KKGP (Nyala)	Speedometer to be reconnected
	BNT583B (Truck)	Tyres, panel beating
Total: 7	Total: 6	
	Mahikeng	
Soft tops: 25	BVC901B (Soft top)	Wheel bearings
Nyalas: 6	JYM474B (Soft top)	Fan fault
Water Canon: 1	BJV139B (Nyala)	Brakes
Trucks: 2	BVH223B (Nyala)	Service and rear door damage
	BJW627B (Nyala)	Ignition
Total: 34	Total: 5	

The second secon	APE
Paarl	
Not operational	Relevant details thereof in each case
194529N (Soft top)	Process to be boarded
BST561B (Soft top)	Process to be boarded
BVB189B (Soft top)	Process to be boarded
BSB957B (Soft top)	Wheel bearings
BTJ794B (Soft top)	Engine
BTG802B (Soft top)	Accident
BVK787B (Nyala)	Service and not roadworthy
BVJ670B (Nyala)	Not roadworthy
BHL336B (Nyala)	Electrical fault
	Alternator fault/oil leak
Total: 10	
George	
BRY826B (Soft top)	Panel beating
BST189B (Soft top)	Mechanical (to be boarded)
	Panel beating
	Mechanical
	Panel beating
	Mechanical
	Panel beating
	Mechanical repair and service
	Mechanical repair and service
	Mechanical repair and service
	Mechanical repair
	Mechanical repair and service
	Mechanical repair and service
	Meditalila i Topali alia del 1100
	m
	Panel beating
	Clutch
	Battery
	Overheating
	Boarding
	Boarding
	Boarding
	Service
	Service
	Overheating
	Breaks
	Engine
	Engine
	Overheating
	Panel beating
	Boarding
	Timing chain
	Engine torque
BVJ647B (Nyala)	Battery
	(c)(ii) Not operational 194529N (Soft top) BST561B (Soft top) BVB189B (Soft top) BSB957B (Soft top) BTJ794B (Soft top) BTG802B (Soft top) BVK787B (Nyala) BVJ670B (Nyala) BHL336B (Nyala) BHL130B (Nyala) Total: 10  George BRY826B (Soft top)

	EASTERN C	CAPE
	Port Elizat	
(c)(i)	(c)(ii)	Determent details thereof in each ages
Currently operational	Not operational	Relevant details thereof in each case
Soft tops: 14	BSD900B (Soft top)	Service
Nyalas: 11	BVF364B (Soft top)	Service
Trucks: 4	BTD224B (Soft top)	Mechanical engine overhaul
Casspirs: 2	BTX814B (Soft top)	Service
Towing Casspir: 1	BVJ711B (Soft top)	Service
Blesbok: 1	BVJ770B (Soft top)	Damaged
	BTX887B (Soft top)	Mechanical
	BTZ974B (Soft top)	Mechanical engine overhaul
	BVB274B (Soft top)	Service
	BVY696B (Soft top)	Damaged
	BSX108B (Soft top)	Boarded
	BRP373B (Soft top)	Boarded
	BSJ831B (Soft top)	Damaged
	BHL313B (Nyala)	Mechanical gear linkage
Total: 33	Total: 14	wicenamesi gear iiinkage
1 4 90(1) 44	East Lond	lon
Soft Tops: 13	BTK829B (Soft top)	Engine fault
Nyalas: 2	BVY717B (Soft top)	Accident damage
Trucks: 2	BVJ705B (Soft top)	Suspension fault
TTUCKS. Z		Engine fault
	BVJ706B (Soft top)	Service
	BVJ707B (Soft top)	
	BTV438B (Soft top)	Suspension fault
	BTX810B (Soft top)	Clutch fault
	BVH537B (Soft top)	Engine fault
	BTD226B (Soft top)	Engine fault
	BTD723B (Soft top)	Boarding process
	BRT210B (Soft top)	Boarding process
	BSD124B (Soft top)	Boarding process
	198430M (Soft top)	Boarding process
	BVH222B (Nyala)	Electrical fault
	108206T (Nyala)	Engine leak
	136626E (Nyala)	Electrical fault
	136595R (Nyala)	Radiator leak
Total: 17	Total: 17	
	Mthatha	
Soft tops: 7	BTV435B (Soft top)	Non - starter
Nyalas: 3	BVC 146B (Soft top)	Computer box
Casspirs: 3	BVJ738B (Soft top)	Electric problem
	BVJ736B (Soft top)	Petrol pump
	BVZ989B (Soft top)	Non - starter
	BTK684B (Soft top)	Engine
	BTD223B (Soft top)	Process of boarding
	BSJ834B (Soft top)	Process of boarding
	BTD724B (Soft top)	Process of boarding
	BVY697B (Soft top)	Brakes
***	BTX811B (Soft top)	Non - starter
	BTZ982B (Soft top)	Process of boarding
	HYC459EC (Soft top)	Body work
	BSX104B (Soft top)	Process of boarding
	BHL203B (Nyala)	Clutch
	ZGV923GP (Nyala)	Gearbox
	BJW608B (Nyala)	Non - starter
Total: 13	Total: 17	10 10 10 10 10 10 10 10 10 10 10 10 10 1

	Queensto	wn .
(c)(i) Currently operational	(c)(ii) Not operational	Relevant details thereof in each case
Soft tops: 5	BVC145B (Soft top)	Body repairs
Nyalas: 4	BVH874B (Soft top)	Service
	BTV441B (Soft top)	Starter
· · · · · · · · · · · · · · · · · · ·	BVJ742B (Soft top)	Roadworthy
	BTM670B (Soft top)	Service
	BBF833B (Motorbike)	Battery fault
	BBF832B (Motorbike)	Battery fault
	BHL233B (Nyala)	Gear links
Total: 9	Total: 8	
	Aliwai No	th
Soft tops: 9	BSJ781B (Soft top)	Mechanical fault (sliding door)
Nyalas: 3	BSJ782B (Soft top)	Engine fault
-	BVH677B (Soft top)	Mechanical fault (suspension)
	BTV436B (Soft top)	Mechanical fault (brakes)
	BVB194B (Soft top)	Mechanical fault (damage repairs)
	BHL200B (Nyala)	Mechanical fault (steering box)
Total: 12	Total: 6	
	Cradock	
Soft tops: 3	BVH235B (Soft top)	Mechanical fault (gearbox)
Nyalas: 1	BTF015B (Soft top)	Mechanical fault (gearbox)
Other: 3	BSJ783B (Soft top)	Funds depleted (+600 000kms)
	BSJ784B (Soft top)	Funds depleted (+620 000kms)
	BHL105B (Nyala)	Air leakage
	CG76FXGP (Nyala)	Air leakage
Total: 7	Total: 6	
	Lusikisik	1
Soft tops: 11	BVC148B (Soft top)	Waiting to be boarded
Nyalas: 2	BHL190B (Nyala)	Steering wheel fault
Truck: 1	BHL319B (Nyala)	Gearbox, steering wheel, suspension
	BJW629B (Nyala)	Gearbox fault
Total: 14	Total: 4	

	MPUMALA	NGA
	Secund	9
(c)(i) Currentiy operational	(c)(li) Not operational	Relevant details thereof in each case
Soft tops: 15	BTN240B (Soft top)	Overheating
Nyalas: 4	BTN241B (Soft top)	Engine fault
	BTZ927B (Soft top)	Panel beating
	BTX944B (Soft top)	Panel beating
	BHL198B (Nyala)	Tyres worn out
Total: 19	Total: 5	
	Middelbu	rg
Soft tops: 26	BTZ931B (Soft top)	Brake system fault
Nyalas: 5	BRL903B (Soft top)	Recommended for boarding
	BWC159B (Soft top)	Panel beating
	BVK624B (Soft top)	Electrical fault/Speedometer
	BVF365B (Soft top)	Gear box fault
	BHL221B (Nyala)	Tyres worn out
Total: 31	Total: 6	
	Kwamhlar	ng <b>a</b>
Soft tops: 21	BRV97 B (Soft top)	Tyres worn out
Nyalas: 7	BTF497B (Soft top)	Recommended for boarding
Trucks: 1	BKV150B (Nyala)	Air pipes
	BKN624B (Nyala)	Wheel binding
	BKV148B (Nyala)	Engine fault
Total: 29	Total: 5	
	Hazyviev	N .
Soft tops: 26	BSC451B (Soft top)	Mechanical repairs
Nyalas: 12	BTD801B (Soft top)	Waiting for registration
	BTD803B (Soft top)	Garage to fix brakes
	BTX941B (Soft top)	Windscreen cracked
	BTZ889B (Soft top)	Speedometer to be reconnected
	BVD335B (Soft top)	Engine fault
	BVD336 B (Soft top)	Engine fault
	BVF181B (Soft top)	Electric wiring fault
·	BVK968B (Soft top)	Engine fault
	BJV748B (Soft top)	Brakes problem
	BWW562B (Soft top)	Overheating
	BWC155B (Soft top)	Panel beating
	CP07VRGP (Nyala)	Hand brake fault
	BHL328B (Nyala)	Tyres worn out
*	BHL054B (Nyala)	Gear box fault
	FK45RLGP (Nyala)	Gear box fault
	BHL046B (Nyala)	Tyres worn out
	BKV147B (Nyala)	Wheel binding
	BJV104B (Nyala)	Transmission oil leak
	BJW568B (Nyala)	Gear box fault
Total: 38	Total: 20	Gear DOX Iduit

	NORTHERN	
	Kimberle	у
(c)(i) Currently operational	(c)(ii) Not operational	Relevant details thereof in each case
Soft tops: 18	BVH191B (Soft top)	Service
Nyalas: 8	BVH536B (Soft top)	Overheating
Water Canons: 2	BTH084B (Soft top)	Service
Fruck: 1	BTB827B (Soft top)	Clutch fault
Casspir: 1	BTB828B (Soft top)	Engine overall
омоори. 1	BTB829B (Soft top)	Engine overall
	BSF068B (Soft top)	Brakes and power loss
	BTZ098B (Soft top)	Oil and water leak
	BRR938B (Soft top)	Gears faulty
	BTT595B (Soft top)	Power loss
Fotal: 30	Total: 10	1 01101 1000
	Upingto	1
Soft tops: 20	CJW403NC (Soft top)	Repair
Nyalas: 4	BSF973B (Soft top)	Engine
TJ C.C.	BSD823B (Soft Top)	Mechanical fault
	BTB439B (Soft top)	Boarding process
	BTB440B (Soft top)	Gearbox
	BTB422B (Soft top)	Shock absorbers
	BTT213B (Soft top)	Mechanical fault
	BTT002B (Soft top)	Engine
	BTS906B (Soft top)	Boarding process
	BVH831B (Soft top)	Mechanical fault
	BSB534B (Soft top)	Steering rack
	BPX988B (Soft top)	Engine repair
	BRR938B (Soft top)	Boarding process
	BTT601B (Soft top)	Pulley and Tensioner
	BTT602B (Soft top)	Engine repair
	BTT603B (Soft top)	Engine repair
	BTY569B (Soft top)	Engine repair
	BJV087B (Nyala)	Engine and gear box repairs
	BJV113B (Nyala)	Refurbish
Total: 24	Total: 19	Refulbish
VIII. 15-7	Kurumar	
Soft tops: 10	BTT598B (Soft top)	Engine overheating
lyalas: 2	BTT599B (Soft top)	Engine over heating
tydias. Z	BTT600B (Soft top)	Engine over heating
	BVB192B (Soft top)	Engine over fleating
	BTZ558B (Soft top)	Engine overall
otal: 12	Total: 5	Ligilic Overall
1-	De Aar	
Soft tops: 8	BTT597B (Soft Top)	Shock absorbers
iyalas RG12: 2	BVF250B (Soft Top)	Repair damages
Vater Canon: 0	BVP387B (Truck)	Service
rucks: 1	BRZ581B (Soft Top)	Engine overall
otal: 11	Total: 4	Linguis Official
	Springbo	le .
Soft tops: 8	BTT597B (Soft Top)	Shock absorbers
lyalas RG12: 2	BVF250B (Soft Top)	Repair damages
Vater Canon: 0	BVP387B (Truck)	Service
rucks: 1	BRZ581B (Soft Top)	Engine overall
Total: 11	Total: 4	Engine Oferall

	LIMPOPO	
	Polokwane	
(c)(i) Currently operational	(c)(ii) Not operational	Relevant details thereof in each case
Soft tops: 4	BPV567B (Soft top)	Starter
Nyalas: 6	BTV233B (Soft top)	Engine fault
1474143. 0	BST223B (Soft top)	Radiator fault
	BTF163B (Soft top)	Engine fault
	BTJ058B (Soft top)	Starter
	BHL284B (Nyala)	Adaptor plate
	BKV125B (Nyala)	Tyres
	BHL089B (Nyala)	Engine fault
	BHL169B (Nyala)	Alternator
	BKB909B (Nyala)	Tyres
	BHL065B (Nyala)	Tyres/starter
	BJV110B (Nyala)	Tyres
	BJW575B (Nyala)	Tyres
	BHL093B (Nyala)	Suspension, starter
	BVJ515B (Nyala)	Speedometer fault
Total: 10	Total: 15	Opecoometer laut
	Thohoyando	
Soft tops: 9	BVJ356B	Mechanical
Nyalas: 4	BTB649B	Breaking system
Tydias. 4	BVB271B	Oil leak
Total: 13	Total: 3	Oli loak
	Burgersfor	
Soft tops: 6	BVF200B (Soft top)	Mechanical
Nyalas: 1	BTY142B (Soft top)	Ball joint
	BHL287B (Nyala)	Radiator and fan broken
	BVK129B (Nyala)	Starter, service
	DW11FZB (Nyala	Accelerator, radiator
Total: 7	Total: 5	/ Noociciator, radiator
	Lephalale	
Soft tops: 6	BTZ987B (Soft top)	No power
Nyalas: 3	BVF366B (Soft top)	Damaged front suspension
	BTV232B (Bus)	No tyres and no back window
Total: 9	Total: 3	THE STATE OF
	Modimolie	
Soft tops: 4	BTX459B (Soft top)	Bearing knock
Nyalas: 2	BVF249B (Soft top)	Sound in engine
	BSJ683B (Soft top)	Windscreen
	BVB155B (Soft top)	Diesel leak
	BTB651B (Soft top)	Oil leak
	BSL719B (Soft top)	No power
	BTY023B (Soft top)	Front suspension
· · · · · · · · · · · · · · · · · · ·	BPG388B (Soft top)	Disc expired
	BHL349B (Nyala)	Overheating
	BKV124B (Nyala)	Starter
	BKV127B (Nyala)	Tyres
Total: 5	Total: 11	1,7.00

	Giyani	
(c)(i) Currently operational	(c)(ii) Not operational	Relevant details thereof in each case
Soft tops: 2	BTB647B (Soft top)	Clutch
Nyala: 1	BTX462B (Soft top)	Clutch
	BTK087B(Soft top)	Engine failure and brakes
	BTG308B (Soft top)	Engine failure
	BTB695B (Soft top)	Panel beating
	BNK440B (Soft top)	Panel beating
	BTS721B (Nyala)	Tyres
	BJW584B (Nyala)	Suspension
	BHL109B (Nyala)	No disc
Total: 3	Total: 9	
	Grobiersda	
Soft tops: 6	0	Not applicable
Nyala: 1	0	Not applicable
Total 7	Total: 0	
	Tzaneen	
Soft tops: 5	BTB695B	Clutch fault
Nyalas: 2	BNK440B	Panel beating
Total: 7	Total: 2	
	Makhado	**
Soft tops: 2	BTJ072B	Engine fault - to be boarded
Nyala: 1	BJV148B	Tyres
Total: 3	Total: 2	

	GAUTENG	1.10
/m\#31	Springs	5 7 19
(c)(i) Currently operational	(c)(ii) Not operational	Relevant details thereof in each case
Soft Tops: 47	BRK360B (Soft Top)	Boarding Process
Nyalas:2- Own Strength	BRS852B (Soft Top)	Boarding Process
Water Canon: 1	BSN634B (Soft Top)	Boarding Process
Loaned – Mob Support	BSP451B (Soft Top)	Boarding Process
Nyalas: 6 Mob Support	BTC949B (Soft Top)	Boarding Process
Nyalas:2 New Generation	BTD196B (Soft Top)	Boarding Process
	BTD199B (Soft Top)	Boarding Process
	BTD201B (Soft Top)	Boarding Process
	DY51GSGP (Soft Top)	Boarding Process
	BVM523B (Soft Top)	Boarded
	BTD222B (Soft top)	Garage - Engine
	BTD980B (Crafter)	Garage - Suspension
	BTD982B (Crafter)	Garage - Suspension
	BTV890B (Soft Top)	Garage – Gear box
	BTW279B (Soft Top)	Garage - Gear Box
	BTW348B (Soft Top)	Garage - Suspension
	BTX338B (Soft Top)	Garage – Cylinder Head
	BTZ342B (Soft Top)	Garage - Mechanical fault
	BVB484B (Soft Top)	Garage – Brake Discs
	BVD103B (Soft Top)	Garage - Gear Box
	BVF983B (Soft Top)	Garage - Cylinder Head
	BVG195B (Soft Top)	Garage - CV Joints
	BVL731B (Soft Top)	Garage - Panel Beating
	DB95NJGP (Soft Top)	Garage – Gear Box
	BHL007B (Nyala)	Not Roadworthy
	BHL011B (Nyala)	Not Roadworthy
	BHL014B (Nyala)	Not Roadworthy
	BHL123B (Nyala)	Oil Leak
	BHL126B (Nyala)	Not Roadworthy
	BHL1191B (Nyala)	Garage - Gear Box
	BHL330B (Nyala)	Not Roadworthy
	BJW582B (Nyala)	Not Roadworthy
	BKV139B (Nyala)	Engine Overall
	BHL112B (Nyala)	Gear Box
	BKV172B (Nyala)	Power Steering Pump
	BDZ442B (Caspir)	Clutch and Brakes
Total: 58	Total: 36	
	Pretoria	
Soft tops: 25	BVR401B (soft top)	Waiting for repair of exhaust
Vyalas: 2	BVR402B (soft top)	Engine
Frucks: 1	BVP706B (soft top)	Electrical fault
	BVP711B (soft top)	Rear wheel brake drum
	BVN615B (Nyala)	Service
Total: 28	Total: 5	- COLLINA

/aWB	Johannesbury	9
(c)(i) Currently operational	(c)(li) Not operational	Relevant details thereof in each case
Soft tops: 76	BDY333B (Casspir)	Breaks and tyres
Nyalas:16 (RG12) 2 (New Gen)	BDZ495B (Casspir)	Clutch
Casspirs: 3 Gemsbok 1	BDV550B (Gemsbok)	Winch broken
Trucks:4	BHL038B (Nyala)	Clutch
	BHL207B (Nyala)	Hydraulic problem and brakes
	BJV147B (Nyala)	Brakes
	BHL326B (Nyala)	Engine Damage
	BHL333B (Nyala)	Power failure
	BJF674B (Nyala)	Starter faulty
	BJF705B (Nyala)	Steering column
	BJV130B (Nyala)	Recommended for boarding
	BSP011B (soft top)	Boarded
	BSP014B (soft top)	Boarded
	BTD187B (soft top)	Boarded
	BTZ633B (soft top)	Boarded
	BTK541B (soft top)	Boarded
	BSN640B (soft top)	Boarded
	BTC577B (soft top)	Boarded
	BTZ634B	Engine fault
	BTD336B	Starter faulty
	BTN336B	Breaking system
	BTZ341B	Engine fault
·	BVS924B	Clutch faulty
	BTZ641B	Gearbox
	BTD285B BTZ340B	Electrical fault
	BTC578B	Panel beating Clutch faulty
	BTZ321B	Starter faulty
	BTZ942B	Panel beating
Total: 102	Total: 29	T aries beauting
	Krugersdorp	
Soft Tops: 32	BHL024B (Soft top)	Gearbox and Electrical Failure
Nyalas: 10	BHL029B (Soft top)	Leaking Transmission Fluid
Casspirs: 2	BHL297B (Soft top)	Diesel Pump Failure Electrical fault
Trucks: 1	BJF681B (Soft top)	Gearbox and Clutch
	BJV143B (Soft top)	Electrical and Transmission Failure
	BKV142B (Soft top)	Clutch and Transmission
	BKV171B (Soft top)	Transmission Fluid Leakage
	BVP395B (Soft top)	Clutch and Gearbox Failure
	BVP807B (Soft top)	Air System Failure/General Repairs
	BVP979B (Soft top)	Service and Air System Failure
	BTN261B (Soft top)	Garage - Alternator Failure
	BVN 566B (Nyala)	Accident
	BVP508B (Nyala)	Brake System Overhaul
	BVP527B (Nyala)	Accident
	BVP528B (Nyala)	Petrol Pump Replacement
	BVP712B (Nyala)	Vehicle Boarded
	BVS404B (Nyala)	Brake System Replacement
	BVS444B (Nyala)	Accident
	BVS511B (Nyala)	Engine Overhaul
	BVS952B (Nyala)	Clutch System Overhaul
Total: 48	BVT639B (Nyala)	Accident
Total: 45	Total: 21	

	Sedibeng	
(c)(i) Currently operational	(c)(ii) Not operational	Relevant details thereof in each case
Soft tops: 35	BVP 174 B (Soft top)	Accident
Nyalas new generation: 02	BTZ 686 B (Soft top)	Mechanical
Nyala RG 12: 04	BVP 537 B (Soft top)	Accident
Trucks: 01	BTZ 344 B (Soft top)	Mechanical
CASSPIR: 01	BVN 754 B (Soft top)	Accident
CANTER: 02	BVR 403 B (Soft top)	Brakes
Water cannons: 00	BVS 958 B (Soft top)	Accident
	BTZ 638 B (Soft top)	Mechanical
	BTC 678 B (Soft top)	Boarded
	BVP 621 B (Hard top)	Mechanical
	BJW 882 B (Hard top)	Mechanical
	BJF 723 B (Hard top)	Mechanical
	BFD 527 B (Hard top)	Mechanical
Total: 45	Total: 13	